



TIME SQUARE 10 SHV REPORT

19.Jan.2026

TIME SQUARE 10 SHV LOCATION




TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV FLOOR PLAN




SITE PROGRESS UP TO 19 Jan 2026



SITE PROGRESS UP TO 19 Jan 2026

BORE PILE FINISHED 15/197p



TOOL BOX MEETING



BORE PILE DRILLING



REBAR INSPECTION



REBAR INSPECTION




REBAR INSPECTION BEFOR CONCRETE




DEPTH INSPECTION BEFORE CONCRETE



BENTONITE SLURRY INSPECTION




BENTONITE SLURRY INSPECTION



CONCRETE INSPECTION



CONCRETE STRENGTH INSPECTION



MOVE IN MATERIALS



MATERIALS CONTROL



MATERIALS CONTROL



CONSTRUCTION ENVIRONMENT




CONSTRUCTION ENVIRONMENT





PASSION FOR PROGRESS!



TIME SQUARE 10
OCEAN VIEW
THE BEST DAY IN OTRES BEACH

THANK YOU!