



TIME SQUARE 10 SHV REPORT

19.April.2026



TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV LOCATION




TIME SQUARE 10 SHV ANOTHER POINT OF VIEW



TIME SQUARE 10 SHV FLOOR PLAN




SITE PROGRESS UP TO 19 April 2026



SITE PROGRESS UP TO 19 April 2026

BORE PILE FINISHED 136/197p

Bored pile progressing



TOOL BOX MEETING



SURVEY INSPECTION



BORED PILE DRILLING



REBAR INSPECTION



REBAR INSPECTION



DEPTH INSPECTION BEFORE CONCRETE



INSTALLING REBAR BEFORE CONCRETE



BENTONITE SLURRY INSPECTION



CONCRETE INSPECTION




CONCRETE STRENGTH TEST



MATERIALS CONTROL



SITE CLEANING




CONSTRUCTION ENVIRONMENT





PASSION FOR PROGRESS!



TIME SQUARE 10 OCEAN VIEW

THE BEST DAY IN OTRES BEACH

THANK YOU!