



TIME SQUARE 10 SHV REPORT

19.May.2026



TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV LOCATION




TIME SQUARE 10 SHV ANOTHER POINT OF VIEW




TIME SQUARE 10 SHV FLOOR PLAN




[illegible]

SITE PROGRESS UP TO 19 May 2026

BORE PILE FINISHED 159/197p




SONIC TEST PROGRESS UP TO 19 May 2026



SONIC TESTING PROGRESS UP TO 19 May 2026

FINISHED 79/197p



TOOL BOX MEETING



SURVEY INSPECTION



BORED PILE DRILLING



REBAR INSPECTION




DEPTH INSPECTION BEFORE CONCRETE



INSTALLING REBAR BEFORE CONCRETE






CONCRETE INSPECTION



MATERIAL CONTROL



CONCRETE STRENGTH TEST



SONIC LOGGING TEST



SITE CLEANING




CONSTRUCTION ENVIRONMENT





PASSION FOR PROGRESS!



TIME SQUARE 10 OCEAN VIEW

THE BEST DAY IN OTRES BEACH

THANK YOU!