




# TIME SQUARE TK TS335

Monthly Report

Date : 2025.AUGUST.29

# SITE LOCATION




# TIME SQUARE 335 ENVIRONMENT



# SOIL EXCAVATION PROGRESS

Up to 29th August 55% done.



# SOIL EXCAVATION PROGRESS

Up to 29th August 55% Finished.




# SOIL EXCAVATION PROGRESS

Up to 29th August 50% Finished.




# SOIL EXCAVATION PROGRESS

Up to 29th August 55% Finished.



# SHORING SYSTEM PROGRESS

Up to 29th August 45% Finished.




# SHORING SYSTEM PROGRESS

Up to 29th August 45% Finished.




# SHORING SYSTEM PROGRESS

Up to 29th August 45% Finished.



# PILE CAP PROGRESS

Up to 29th August 30% Finished.




# PILE CAP PROGRESS

Up to 29th August 30% Finished.



# PILE CAP PROGRESS

Up to 29th August 30% Finished.



**Pouring Concrete on 26th August.**

# MATERIALS SUPERVISION



