



TIME SQUARE

TK TS335

Weekly Report

Date : 2026.Mar.09

SITE LOCATION



SITE LOCATION




TIME SQUARE 335 ENVIRONMENT



TOOL BOX MEETING



SITE CLEANING




4F SAFETY SCAFFOLDING PROGRESS

Up to 09th Mar 100% completed




4F SAFETY SCAFFOLDING PROGRESS

Up to 09th Mar 100% completed



4F SAFETY SCAFFOLDING PROGRESS

Up to 09th Mar 100% completed




Up to 09th Mar 100% completed


[illegible]

NOTES:

1. CONCRETE STRENGTH 40MPA (CYL. AGER 28DAYS)
2. REBAR TENSILE STRENGTH 580MPA
3. LAP SPICE 50D (ALLOWED ONLY 50% PER ANY POSITION)



DETAIL W/1 REINFORCEMENT UNDER 3RD FLOOR TO UNDER 5TH FLOOR
SCALE 1/75




3F LIFT WALL PROGRESS

Up to 09th Mar 100% completed



3F LIFT WALL PROGRESS

Up to 09th Mar 100% completed




3F LIFT WALL PROGRESS

Up to 09th Mar 100% completed





3F LIFT WALL PROGRESS

Up to 09th Mar 100% completed




Up to 09th Mar 100% completed

Up to 09th Mar 100% completed



4F SLAB PROGRESS

Up to 09th Mar 100% completed




4F SLAB PROGRESS

Up to 09th Mar 100% completed




4F SLAB PROGRESS

Up to 09th Mar 100% completed




4F SLAB PROGRESS

Up to 09th Mar 100% completed





Up to 09th Mar 100% completed




3F COLUMN PROGRESS

Up to 09th Mar 100% completed



3F COLUMN PROGRESS

Up to 09th Mar 100% completed



3F COLUMN PROGRESS

Up to 09th Mar 100% completed




3F COLUMN PROGRESS

Up to 09th Mar 100% completed




3F COLUMN PROGRESS

Up to 09th Mar 100% completed




3F-4F RAMP PROGRESS

Up to 09th Mar 100% completed




3F-4F RAMP PROGRESS

Up to 09th Mar 100% completed



3F-4F RAMP PROGRESS

Up to 09th Mar 100% completed



3F-4F RAMP PROGRESS

Up to 09th Mar 100% completed



