

TIME SQUARE
TK TS335

Weekly Report

Date : 2026.June.09

SITE LOCATION



SITE LOCATION



TIME SQUARE 335 ENVIRONMENT








TOOL BOX MEETING








SITE CLEANING







8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Slab Rebar installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Slab Rebar installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Slab Rebar installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F PT Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F PT Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F MEP Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F MEP Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F MEP Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed






8F Column Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Column Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Column Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F RC Wall Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F RC Wall Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F RC Wall Starter Rebar Installation (Done)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Slab Side Formwork installation (Done=80%)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Slab Side Formwork installation (Done=80%)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F Slump Test before Casting Concrete

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Casting Concrete (1st Cast = 40cm)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Casting Concrete (1st Cast = 40cm)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed








8F Casting Concrete (1st Cast = 40cm)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed







8F Casting Concrete (Imprint Hole Concrete)

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed









8F Slab Concrete Curing

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed






8F Progress Work

8F STRUCTURE PROGRESS

Up to 09th JUNE 85% completed



1F FINISHING WORK PROGRESS

Up to 09th JUNE 60% completed








1F Finishing Work Electric Room : Apply skim coat (Done)

1F FINISHING WORK PROGRESS

Up to 09th JUNE 60% completed






1F Finishing Work Electric Room : Apply skim coat (Done)

1F FINISHING WORK PROGRESS

Up to 09th JUNE 60% completed







1F Finishing Work Electric Room : Apply Painting (Done)

1F FINISHING WORK PROGRESS

Up to 09th JUNE 60% completed








1F Finishing Work Electric Room : Apply painting & skim coat (Done)


1F FINISHING WORK PROGRESS

Up to 09th JUNE 60% completed




1F Finishing Work Electric Room : Apply painting & skim coat (Done)

INSPECTION WORK







8F Beam Rebar Inspection

INSPECTION WORK









8F Beam Rebar Inspection

INSPECTION WORK







8F Slab Rebar Inspection

INSPECTION WORK







8F Column & RC wall Rebar Inspection

INSPECTION WORK








8F Setting out Inspection

INSPECTION WORK







8F Setting out Inspection

INSPECTION WORK







8F MEP Inspection

INSPECTION WORK







8F PT Inspection

INSPECTION WORK







8F PT Inspection

MATERIALS SUPERVISION










PASSION FOR PROGRESS



