

TIME SQUARE 410 (8)

MONTHLY REPORT

29. AUGUST. 2025




LOCATION OF CONSTRUCTION SITE




PROGRESS PLAN OF PILE WORK

- Estimated to be completed on the 25th October 2025




MAIN PILE



PILE PROGRESS UP TO 29. AUGUST. 2025


Completed 26/76 Piles



PILE PROGRESS UP TO 29. AUGUST. 2025


Completed 26/76 Piles

MAIN PILE




CBP PROGRESS UP TO 29. AUGUST. 2025

Completed 328p/328p (Done)



CBP PROGRESS UP TO 29. AUGUST. 2025

Completed 328p/328p (Done)





PILE SETTING OUT WORK



DRILLING WORK



REBAR FRABRICATION WORK



BENTONITE SLURRY INSPECTION



Bentonite inspection: Before drilling, before casting concrete.

CASTING CONCRETE




HSE INSPECTION



Toolbox meeting: Checking up on safety environment, PPE and front site cleaning .

MATERIAL INSPECTION



TOP VIEW





Time Square 8

The Fastest Selling Project

in Phnom Penh



BUILD FOR PASSION!



THANK YOU!